ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra

Street ID	Street Name	Significant Landmark
W1683, W1064, W1701, W0976, W1697, W1066, W1681, W	NA	Anam enclave

Segment No.	Total Length (m)
6/C-W1683/S084437	364.26

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	72.43	77.636916	13.049871	77.636856	13.049219	W0976	W1072
2	118.43	77.638040	13.050181	77.637954	13.049114	W1064	W1072
3	38.42	77.637577	13.049901	77.637666	13.050238	W1064	W0976
4	41.36	77.637292	13.049924	77.637389	13.050286	W1064	W0976
5	44.98	77.636994	13.049950	77.637094	13.050344	W1064	W0976
6	48.64	77.636707	13.049975	77.636798	13.050406	W1064	W0976

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to road & drain at Anam enclave in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	2000000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements to road & drain at Anam enclave in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-15-000005

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-PMT/WO/300/2015-16	23/03/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
23/03/2016	22/03/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)

R SATEESH 0.00

Phone No. **E-Mail ID**

9341705164

Field Inspection Details

Number of Trees	Any Other Information	Name
15		KRISHNAPPA
Date of Inspection	**Remarks**	
24/09/2016	COMPLETED	

Category	Image	Photo Remark
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1683, W1064, W1701, W0976,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	24/09/2016	24/10/2016	COMPLETED
SE	VASU K M	24/09/2016	24/10/2016	COMPLETED
EE	YARAPPA REDDY	24/09/2016	24/10/2016	COMPLETED
AEE	J N LOKESH	24/09/2016	24/10/2016	COMPLETED
AE	KRISHNAPPA	24/09/2016	24/10/2016	COMPLETED
AE	KRISHNAPPA	24/09/2016	24/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W1683, W1064, W1701, W0976,